



This image shows a cross-section of a concrete slab with a significant void. The void is a large, dark, irregular cavity that has formed within the concrete structure, likely due to honeycombing or a casting defect. The surrounding concrete appears light gray and textured.

